

I2C

Reference:UM10204.pdf

Slave-address is 7bit.

This is placed to [bit7-bit1].

In case of h78, write is b11110000(hF0) and read is b11110001(hF1).

Please refer UM10204.pdf in case of 10bit-address.

When PropForth4.6, _eewrite is below;

```
: _eewrite
  80 8 0
  do
    2dup and
    if
      _sdah
    else
      _sdal
    then
      _sclh _scll 1 rshift
  loop
  2drop
  _sdai _sclh _sda? _scll _sdal _sdao    <-- When scl is high, sda?
;
```

This is Forth word.

On PropForth5.5 _eewrite is assembler word.

¥ _eewrite (c1 -- t/f) write c1 to the eeprom, true if there was an error

¥

¥

:asm

__x02sda jmp # __x0C

 h20000000

__x03scl h10000000

__x04delay/2 hD

¥ this delay makes for a 400kHz clock on an 80 Mhz prop

¥

__x0Edelay/2

 mov \$C_treg6 , __x04delay/2 <-- 4ticks

__x0D djnz \$C_treg6 , # __x0D <-- 4ticks

```

__x0Fdelayret
    ret                <-- 4ticks
¥
__x0C
    mov    $C_treg3 , # h8
¥
__x0B
    test   $C_stTOS , # h80    wz
    muxnz outa , __x02sda
¥
    jmpret __x0Fdelayret , # __x0Edelay/2
¥
    or     outa , __x03scl
¥
    jmpret __x0Fdelayret , # __x0Edelay/2
    jmpret __x0Fdelayret , # __x0Edelay/2
¥
    andn   outa , __x03scl
    shl    $C_stTOS , # 1
¥
    jmpret __x0Fdelayret , # __x0Edelay/2
¥
    djnz   $C_treg3 , # __x0B
¥
    andn   dira , __x02sda
    test   __x02sda , ina wz
    muxnz  $C_stTOS , $C_fLongMask
¥
    jmpret __x0Fdelayret , # __x0Edelay/2
¥
    or     outa , __x03scl
¥
    jmpret __x0Fdelayret , # __x0Edelay/2
    jmpret __x0Fdelayret , # __x0Edelay/2
¥
    andn   outa , __x03scl
¥
    jmpret __x0Fdelayret , # __x0Edelay/2
    andn   outa , __x02sda
    or     dira , __x02sda
¥
¥
    jexit
¥
;asm _eewrite

```

__x0Edelay/2 is 60ticks[4 + (4 X 13) + 4].

1-clock pulse is 240ticks(60 X 4)

In case of 80MHz(5MHz Xtal), 3usec. Clock frequency is 333.3kHz.
In case of 96MHz(6MHz Xtal), 3usec. Clock frequency is 400kHz.

And acknowledge is incorrect on _eewrite of PF5.5.
When clock-pulse is High, it should get SDA.
Refer section3.1.6 on UM10204.pdf.

But I have never get acknowledge-error by using current _eewrite.
Maybe this will be fix on next version.

!! I have acknowledge-error touch-sense-controller(RN6011). But I think this chip is broken.