Last page of log from teraterm showing input from nRF receiving no interupts
```
Packets received: 35RSSI: -255
Packets received: 35RSSI: -255
Packets received: 35RSSI: -255
Packets received: 35RSSI: -255
Packets received: 35RSSI: -255
Packets received: 35RSSI: -255
Packets received: 35RSSI: -255
Packets received: 35RSSI: -255
Packets received: 35RSSI: -255
Packets received: 35RSSI: -255
Packets received: 35RSSI: -255
Packets received: 35RSSI: -255
Packets received: 35RSSI: -255
Packets received: 35RSSI: -255
Packets received: 35RSSI: -255
Packets received: 35RSSI: -255
Packets received: 35RSSI: -255
Packets received: 35RSSI: -255
Packets received: 35RSSI: -255
Packets received: 35RSSI: -255
Packets received: 35RSSI: -255
Packets received: 35RSSI: -255
Packets received: 35RSSI: -255
Packets received: 35RSSI: -255
Packets received: 35RSSI: -255
Packets received: 35RSSI: -255
Packets received: 35RSSI: -255
Packets received: 35RSSI: -255
Packets received: 35RSSI: -255
Packets received: 35Received packet on pipe 0 from node $E700000:      E7%   .
     E7&   .     54'   T     45(   E    53)   S     54*   T     30+   0     30,
     0     30-   0"    37.   7RSSI: -255
Packets received: 36RSSI: -255
Packets received: 36RSSI: -255
Packets received: 36RSSI: -255
Packets received: 36RSSI: -255
Packets received: 36RSSI: -255
Packets received: 36RSSI: -255
Packets received: 36RSSI: -255
Packets received: 36RSSI: -255
Packets received: 36RSSI: -255
Packets received: 36RSSI: -255
Packets received: 36RSSI: -255
Packets received: 36RSSI: -255
Packets received: 36RSSI: -255
Packets received: 36RSSI: -255
Packets received:üSerial terminal started
nRF24L01+ driver started
Press any key to begin receiving
showing received no interupts
```