Translator Enabled

8-pin bypass header and 2-pin translator header installed. Jumper *not* installed.

Translator Disabled

Jumper installed on 2-pin translator header.