
Direct connection to PC via USB-RS232 (This connection is working without any problems)

This block diagram below illustrates the connections from the Basic stamp board via USB / Serial port connected directly to the PC and the VB program is working in this way.



Connecting the PC via RS-485 modem to run the VB program

The block diagram illustrates the connection that it is not working???

