



To use CMOS version of Si570:
 Remove R25 and U8 from circuit board
 and jumper between hole of R25
 and hole connected to U8 pin 5