
Screen went to garbage setting trigger with 1khz signal and the following settings. Setting Level to Normal and it cleaned up and scope worked fine.



Screen clipping taken: 12/8/2009, 11:59 AM

Channel 1 has an offset when Probe Gain at 10x Offset is not there in 1x gain.

