



Q1. How does LM324 connect to 12-bit A/D?

Q2. Am I missing a filter between sensor & A/D?

Q3. Measurement systems instrumentation amp is different than the one microchip suggests @

www.microchip.com/downloads/en/appnotes/00695a.pdf. (page 8 of 12, Aug 05)

Q4. Is there an advantage of one over the other?

Is there sample code and wire hook ups to connect the 12-bit A/D to the basic stamp & EEPROM to store and display data?